











A=16  8,0 x 30mm	B=02  3,5 x 30mm	C=02  3,0 x 16mm	D=01  4,0 x 40mm	E=01 
F=20  8,0 x 8,0mm	G=14 	H=14 	I=02  4,0 x 40mm	J=08  4,0 x 16mm
L=01 	M=04 	N=06  4,0 x 25mm	O=02 	P=02 


1




G=03




M=02





2



M=02



3



J=04



4,0 x 16mm



O=02



G=03



4



A=02








8,0 x 30mm

I=02








4,0 x 40mm


5



6



7



C=02




3,0 x 16mm


L=01



8




8X




G=08



9



01



A=06





8,0 x 30mm

H=08



10




F=20




8,0 x 8,0mm


06



11



12



P=02



J=04



4,0 x 16mm

N=06



4,0 x 25mm

