













A=32  8,0 x 30mm	B=08  8,0 x 50mm	C=06  4,0 x 25mm	D=35  4,0 x 30mm
E=44  4,0 x 35mm	F=04  7,0 x 50mm	G=16  7,0 x 50mm	H=01 










01











A=32






8,0 x 30mm




02




03






04






E=06



4,0 x 35mm




05







06

E=06



4,0 x 35mm





07

F=04




7,0 x 50mm


H=01



08



D=07




4,0 x 30mm

D




7x

09




C=06




4,0 x 25mm

E=06




4,0 x 35mm




a:




b:




10




11




12




E=10




4,0 x 35mm



13




G=04




7,0 x 50mm

H=01



14




B=04




8,0 x 50mm

E=06




4,0 x 35mm



4x


B




6x

E


15



D=08




4,0 x 30mm




8x


D



16




G=04




7,0 x 50mm

H=01



17




B=04





8,0 x 50mm



E=04




4,0 x 35mm



18



D=04



4,0 x 30mm

